



Has conducted a quality program assessment of

P.Y. Oiltools Sdn Bhd

Located At

Lot No. 84/85, Light Industrial Area Sungai Bera, Anduki , Seria ,
KB1933 , Brunei , South East Asia and Pacific Rim (SEAP)

The quality program has been surveyed and found to be in compliance with the requirements stated within Grant Prideco™ Licensee Quality Program Requirement HLAP01 and associated documents. This facility is authorized and licensed to produce Grant Prideco™ products as described in the Technology License Agreement and as listed within the Grant Prideco Licensee Application.

It is the licensee's responsibility to ensure acceptable qualifying connections have been submitted to Grant Prideco™, and the resulting documentation appropriately maintained. Qualified connections shall be posted on the Grant Prideco Licensee Locator map at <http://www.nov.com/GrantPrideco/Locator.aspx>

11 Nov 2023
Expiration Date

Certificate 17-1368d

Shankar Bhukya

Shankar Bhukya
Certified Licensee Auditor

Anselmo Valadez

Anselmo Valadez
Licensee Services Manager

