

Has conducted a quality program assessment of

## PT OMS Oilfield Services

Located At

Jl.Mulawarman No. 115. RT. 23, Batakan Kecil, P.O. Box 469 ,  
Balikpapan , 76115 , Indonesia , South East Asia and Pacific Rim  
(SEAP)

The quality program has been surveyed and found to be in compliance with the requirements stated within Grant Prideco™ Licensee Quality Program Requirement HLAP01 and associated documents. This facility is authorized and licensed to produce Grant Prideco™ products as described in the Technology License Agreement and as listed within the Grant Prideco Licensee Application.

It is the licensee's responsibility to ensure acceptable qualifying connections have been submitted to Grant Prideco™, and the resulting documentation appropriately maintained. Qualified connections shall be posted on the Grant Prideco Licensee Locator map at <http://www.nov.com/GrantPrideco/Locator.aspx>

19 Jun 2025  
Expiration Date

Certificate 17-1361d

*Shankar Bhukya*

Shankar Bhukya  
Certified Licensee Auditor

*Anselmo Valadez*

Anselmo Valadez  
Licensee Services Manager

